



रामगुंडम खनिजसुशोधा एवं रसायन लिमिटेड

RAMAGUNDAM FERTILIZERS AND CHEMICALS LIMITED

GLIMPSES OF MOCK DRILL CONDUCTED AT RAMAGUNDAM UNIT (AUGUST-2023)

			
<p>Time: 16:03 Hrs. Incident Location where Ammonia is leaking</p>	<p>Time: 16:03 Hrs. First Observer informing to the Shift In-Charge(Production) & Fire Control Room</p>	<p>Time: 16:06 Hrs. Arrival of fire tender to location of incident</p>	<p>Time: 16:06 Hrs. Fire team in Action</p>
			
<p>Time: 16:08 Hrs. Fire Control Room Operator received the emergency call and communicated the same to the PHC, Water Block Control Room and Rescue Coordinator</p>	<p>Time: 16:08 Hrs. First Turnout Initiated from the Fire Station</p>	<p>Time: 16:08 Hrs. Ambulance with medical staff reached at the Incident location</p>	<p>Time: 16:09 Hrs. Covering the leakage from all sides with water curtains</p>
			
<p>Time: 16:06 Hrs. Rescue Coordinator liaising with the Unit Head, Fire Station and Emergency Control Room</p>	<p>Time: 16:06 Hrs. Site Main Controller liaising with the Incident Controller, Rescue Coordinator and other Key members</p>	<p>Time: 16:09 Hrs. Technical Building persons gathered at Assembly Point</p>	<p>Time: 16:09 Hrs. Plant persons gathered at Assembly Point</p>
			
<p>Time: 16:09 Hrs. Fire Crew sharing information with the Shift In-charge(Fire & Safety) and Fire Control Room</p>	<p>Time: 16:09 Hrs. Security Team in Action</p>	<p>Time: 16:20 Hrs. Reporting of incident particulars to Chief Incident Controller</p>	<p>Time: 16:21 Hrs. Debriefing meeting with Chief Incident Controller</p>